


6695 Taylor Rd. Blacklick, OH 43004 www.besalighting.com

Caution: Turn off power to electrical box before installing

- 1. Carefully unpack parts. Loosen Allen Head Screws (F) to release the Mounting Plate (A) from Canopy.
- 2. Secure the Mounting Plate (A) to the Electrical Supply Box with Machine Screws (B) provided.
- 3. Attach the fixture Ground wire to the supply ground and secure with Wire Nut Connector (C).
- 4. Connect the fixture conductors to the supply conductors with Wire Nut Connectors (D) as shown: White fixture wire to white supply wire and black fixture wire to black supply wire. Carefully push wires and wire nuts back into outlet box.
- 5. Position the Canopy (E) over the Mounting Plate and secure by tightening the Allen Head Screws (F) with the Allen Wrench provided.
- 6. Install Glass Shade onto Canopy and secure with Decorative Threaded Socket Cover (G).



NOTE:

Glass Shade is for instructional purposes. Actual Glass Shade may vary in size and shape.